



1 Controller Drives 4 AUC3. Each AUC3 Connects to 1 Miner. 5 Miners can be daisy Chained. For a single Miner you need 1 Controller, 1 AUC and 1 Power Supply. 1 Controller and 4 AUC can drive 20 Miners. 10 Miners would require 2 AUC and 1 controller as shown above.